

QSD/QSP Program Overview

Requirements for becoming a Qualified SWPPP Developer (QSD)
or a Qualified SWPPP Practitioner (QSP)

QSD Qualifications: (Effective Now)

1. Reg. Civil Engineer
2. Reg. Professional Geologist
3. Reg. Landscape Architect
4. Reg. Professional Hydrologist
5. Certified Professional in Erosion and Sediment Control (CPESC)
6. Certified Professional in Storm Water Quality (CPSWQ)
7. Professional in Erosion and Sediment Control Registered through NICET

AND

Must attend a state-sponsored or approved training course and pass the state QSD exam by 9/2/2011

QSP Qualifications: (Effective on 9/2/2011)

Be a QSD

OR OBTAIN

1. Certified Erosion, Sediment, and Storm Water Inspector (CESSWI)
2. Certified Inspector of Sediment and Erosion Control (CISEC)

AND

Must attend a state-sponsored or approved training course and pass the state QSP exam by 9/2/2011

To prepare and certify a SWPPP as of July 1, 2010, you must have the QSD credentials shown in the box on the left and attend and pass a training course and state exam by 9/2/2011. Anyone can implement the SWPPP in the field now; but persons working in the field must become a QSP by 9/2/2011 (see box on right side above).